

65

STATUS OF DAMAGED TRANSFORMERS AS ON 30-01-2017

S.N O.	NAME OF SUB- STATION	CAP (KVA)	Name of Sub- Division	DATE OF DAMAGE	No of Consumers	Expected date of Delivery
1	Hurpora Dachnoo	63	Shopian	21-01-2017	43	03-02-2017
2	Vishkhal	100	Keller	23-01-2017	57	04-02-2017
3	Wangam Khar Moti.	63	Shopian	23-01-2017	42	05-02-2017
4	Chakoora	100	Shopian	23-01-2017	65	05-02-2017
5	Kareewa Manfoo	100	Keller	23-01-2017	66	04-02-2017
6	Amshipora chauhan	63	Shopian	23-01-2017	51	04-02-2017
7	Gadipora	100	Shopian	23-01-2017	71	05-02-2017
8	Herman	100	Chitragam	24-01-2017	69	06-02-2017
9	Cheki Sidiq Khan	63	Chitragam	25-01-2017	55	02-02-2017
11	Batmaran	63	Keller	27-01-2017	54	07-02-2017
12	Nadpora	63	Keller	28-01-2017	51	04-02-2017
13	Saidpora	100	Shopian	28-01-2017	71	08-02-2017
14	Babapora	100	Chitragam	28-01-2017	76	08-02-2017
15	Keegam	100	Keller	28-01-2017	65	09-02-2017
16	Ronipora	100	Shopian	28-02-2017	61	09-02-2017
17	Rakpora	25	Shopian	28-02-2017	15	08-02-2017
18	Jamia Laing	400	Shopian	29-01-2017	246	09-02-2017
19	Rawalpora Shan Mohalla	100	Shopian	30-01-2017	67	10-02-2017
20	Dvegam	63	Keller	at site		
21	Meemender Panchayat	250	Shopian	at site		
22	Meemender Bren	100	Shopian	at site		